## Instrumentation Drivers - Issues

| # | Tracker | Status | Priority | Subject | Assignee | Updated |
|---|---------|--------|----------|---------|----------|---------|
| 13462 | Bug | New | Normal | 57 -97 errors on raw/triggered data channels > 6 | | 08/05/2016 03:14 PM |
| 13456 | Bug | Resolved | Normal | 80MHz Digitizer requires repeating commands for re-arming twice | Dennis Nicklaus | 08/05/2016 03:10 PM |
| 13457 | Bug | Resolved | Normal | 80MHz digitizer driver should sanity check Nchannels setting | Dennis Nicklaus | 08/05/2016 03:03 PM |
| 12763 | Bug | Accepted | Normal | Raw data device does not support channels | John Diamond | 05/25/2016 12:17 PM |
| 12753 | Bug | Resolved | Normal | 80MHz board driver could be a little more forgiving of mistakes. | John Diamond | 05/23/2016 02:38 PM |
| 12754 | Bug | New | Normal | slowness of init of 80MHz driver ?? | John Diamond | 05/23/2016 02:18 PM |